



CLEANING REPORT - Grocery Condensers

18150119098

Reference Number:	20200730-18150119098
Form Name:	CLEANING REPORT - Grocery Condensers
Submitter Name:	Matt Jacobs (matt.jacobs@northeastcoil.com) matt.jacobs@northeastcoil.com
Submission Date:	Jul 30, 2020 2:04:48 PM EDT
Location:	33 Enterprise Dr, Arundel, ME 04046, USA Jul 30, 2020 2:04:34 PM EDT [View Map]

STORE INFORMATION

Cleaning Date:	Jul 30, 2020
Store Name:	Customer
Store Number:	0000
Address:	123 Main St
Lead Technician:	Jon Holmes
Technicians:	Zachary Lacroix Brian Dunn

UNIT INFORMATION

UNIT INFORMATION

1 OF 9

Unit Name:	Rack Condenser - 1
Type of System:	Rack Condenser

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Extremely Dirty
Matted Coil

Location of fan(s) not running:

3

Misc. Notes

UNIT INFORMATION

2 OF 9

Unit Name:

Split Condenser - 1

Type of System:

Mini Split Condenser

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

3 OF 9

Unit Name:

Split Condenser - 2

Type of System:

Split Condenser

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil

Location of fan(s) not running:

2

Misc. Notes

UNIT INFORMATION

4 OF 9

Unit Name:

HVAC w/ Multi Coil Condenser - 1

Type of System:

HVAC (Multi-Coil Condenser)

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil
Bent Fins

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

5 OF 9

Unit Name:

HVAC w/ V Coil Shaped Condenser - 1

Type of System:

HVAC

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

6 OF 9

Unit Name:

HVAC - 3

Type of System:

HVAC

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil
Bent Fins

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

7 OF 9

Unit Name:

HVAC w/ Micro Channel Coil - 4

Type of System:

HVAC

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil
Bent Fins

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

8 OF 9

Unit Name:

Air Handler Unit - 1

Type of System:

AHU

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Matted Coil

Location of fan(s) not running:

Misc. Notes

UNIT INFORMATION

9 OF 9

Unit Name:

Air Handler Unit - 2

Type of System:

AHU

Image of Unit:



Before Cleaning Images:



After Cleaning Images:



Unit Condition:

Dirty
Fan(s) not running at time of cleaning

Location of fan(s) not running:

Misc. Notes

SYSTEM QUALITY CHECK

All Units Have Been Inspected for Quality of Cleaning: Yes

Area Around Unit Has Been Properly Cleaned: Yes

All Units That Were Found ON, Have Been Switched Back to the ON Position: Yes

SIGNATURE

Lead Technician Name:

Jon Holmes

Date:

Jul 30, 2020 1:00:00 PM EDT

Signature:

Jon Holmes

Manager Name:

Michael Smith

Date:

Jul 30, 2020 2:30:00 PM EDT

Signature:

Michael Smith